

TECHNICAL SERVICE BULLETIN

NO.

73-D-2



Austin MG

March, 1973

SUBJECT:

REAR BAND ADJUSTMENT -
AUTOMATIC TRANSMISSION

MODELS:

AUSTIN MARINA

Please note that a correction should be made to section 44-30-10 of the Austin Marina manual, Part No. AKD 7975.

Item 3 states: "Slacken the adjusting screw two complete turns and tighten the locknut." This should read one complete turn.

H.C.T.