

TECHNICAL SERVICE BULLETIN

74-A-6

NO.



Austin MG

SEPTEMBER, 1974

SUBJECT:

AUSTIN MARINA HEAT SHIELD LEAKAGE

MODELS:

MARINA

THE DIAGRAM BELOW ILLUSTRATES A SUGGESTED METHOD TO OVERCOME OIL LEAKAGE FROM THIS POINT.

IN THE EVENT THIS SHOULD BE REQUIRED DURING WARRANTY, A TIME OF 0.60 HOURS WILL BE ALLOWED FOR THE COMPLETE MODIFICATION.

PARTS REQUIRED:

1. ADAPTOR PLATE – PART NO. HAC103
2. FOUR 1/8 POP RIVETS.
3. TWO PAPER GASKETS PART NO. 12G4137

