

TECHNICAL SERVICE BULLETIN

NO.

74-G-1



Austin MG

February, 1974

SUBJECT:

MARINA HEATER INTAKE APERTURE

MODELS:

AUSTIN MARINA

In areas where snowfall is not uncommon, the possibility exists where snow and ice can become impacted in the heater intake, causing a restriction and, in some cases, failure of the blower motor.

A simple screen is available, Part No. HAC 102, which fits over the existing panel and under the intake aperture. Warranty claims will be accepted for this modification as follows:

Fault Code - 8N1

Labor Allowance - 0.20 hours

Parts - One (1) of Part No. HAC 102