

TECHNICAL SERVICE BULLETIN

NO.

75-A-2



Austin MG

March, 1975

SUBJECT:

ENGINE OIL PUMP STUD NUTS

MODELS:

MGB & MARINA

On completion of any work which necessitates the removal of the engine oil pump, it is essential that all three oil pump stud nuts are torqued to equal value.

The torque figure remains at 14 lbs. ft.

Failure to comply with this requirement could result in rapid wear and premature failure of the pump assembly.

PB 34/A