

TECHNICAL SERVICE BULLETIN

NO. 75-A-4



Austin MG

July, 1975

SUBJECT:

CYLINDER HEAD TORQUE

MODELS:

ALL MODELS

Until further notice, we would request that the cylinder head torque be checked during pre-delivery and again at the 1000 mile inspection.

New equipment is under consideration at the factory, which should negate this operation, but for the time being it is imperative that this be done during PDI.

J.P.