

# TECHNICAL SERVICE BULLETIN

75-C-5

NO.



# Austin MG

December, 1975

## SUBJECT:

## MODELS:

HEATER INTAKE APERTURE SCREEN

AUSTIN MARINA

We would like to remind Dealers that in areas where heavy snowfall is not uncommon, the possibility exists where snow and ice can become impacted in the heater intake causing a restriction, and in some cases, failure of the blower motor.

A protective screen is available, Part No. HAC-102, which fits over the existing panel and under the intake aperture. Screens, Part No. HAC-102, are available from your Distributor.

Warranty claims will be accepted for this modification as follows:

Labor Allowance: 0.20 hrs.  
Parts - 1 of Part #HAC-102

J.P.