

Date of Issue: February, 1937

Service Information Sheet No. 42

VALVE ROCKER RETURN SPRINGS

It has been found as a result of a series of tests and experiments that the omission of the valve rocker return springs does not detract in any way from the efficiency of the TA Series Midget and SA Type Two-litre engines.

In consequence of these findings, Agents are notified that in future these springs will not be fitted or supplied for service requirements.

Should any difficulty occur due to the breaking of any one spring it is permissible to remove the complete set.