

Date of Issue: May, 1947

Service Information Sheet No. 68

BRAKE MASTER CYLINDERS

When assembling push rod to Lockheed brake master cylinder, care should be taken to see that the rubber boot is assembled with the vent hole at the bottom.

