



# DEALER AIDS AND DISTRIBUTION INFORMATION

MO.	YEAR
02	1975

SUBJECT:

SPECIAL TOOL NO.18G47BG MODIFICATION  
AND REPLACED BY 18G47BP

FILING:

DEPARTMENT: Service


SECTION: Special Tools

ISSUE:

**ST-3**

As a result of a modified first motion shaft, Tool No.18G47BG is discontinued. Tool No.18G47BP will be supplied instead. Please make note of this change in your tool listing under section, "Special Tools".

To modify the existing Tool No.18G47BG, enlarge center hole of support plate to 18mm as shown:



Enlarge ID  
to 18mm

This tool will now service original and latest type first motion shafts.

REK