

The drain plug has been deleted from the manual gearbox on the Austin Marina as it is considered unnecessary to replace the oil at servicing intervals. The gearbox will now require topping up only.

J.P.