

TECHNICAL SERVICE BULLETIN

74-D-8

NO.



Austin MG

August, 1974

SUBJECT:

GEARBOX CENTER BEARING TO CIRCLIP END-FLOAT


MODELS:

MARINA

In order to facilitate adjustment of the mainshaft center bearing, the tolerance has been increased from .000/.002 to .000/.004.

The current range of selective washers remains unchanged.

Refer to Page 37-20-04 of the Workshop Manual - Part #AKD 7975.



PB/31 D