

TECHNICAL SERVICE BULLETIN

74-D-9

NO.



Austin MG

August, 1974

SUBJECT:


GEARBOX REMOTE CONTROL LINKAGE
MANUAL TRANSMISSION

MODELS:

MARINA

If the roll pin securing the gear lever yoke to the selector shaft is removed in service, it must be discarded and replaced with a new pin. The part number of the pin is RZS 1216.

NOTE: Refitment of the old pin can result in difficult gear engagement or failure of the pin due to movement between the yoke and selector shaft.



PB/31 D