

# TECHNICAL SERVICE BULLETIN

75-D-6

NO.



# Austin MG

September, 1975

SUBJECT:

CLUTCH OIL CONTAMINATION

MODELS:

AUSTIN MARINA

A modified gear box first motion shaft oil seal was introduced at the following gear box number to avoid complaints of oil leakage and subsequent clutch contamination:

18V 260374

With immediate effect, all seals supplied by the Parts Department will be to the latest specification. The part number, however, remains unchanged and is 22G2028.

Any failures encountered after this change point must be notified immediately to your Distributor on a Product Defect Report form, accompanied by the displaced parts.

TB/4/8/15/75/33