

# TECHNICAL SERVICE BULLETIN

73-G-7

NO.



# Austin MG

March, 1973

**SUBJECT:** MG MIDGET CLUTCHES -  
WARRANTY CLAIMS

**MODELS:**  
MG MIDGET

Examination of recently returned material indicates that clutch components are being improperly replaced under warranty as the failure appears to have come about through conditions of use and in some instances misdiagnosis.

Effective immediately, all clutch claims for MG Midget are subject to component inspection and authorization by Distributors' service representatives. It may be necessary in some cases to charge the owner for the work, pending such verification.

J.P.