



Austin MG

June, 1975

SUBJECT:

FRONT NUMBER PLATE MOUNTING
POSITION

MODELS:

1500 CC MIDGET

Cases have been reported of a tendency for the 1975 1500 CC Midget to overheat at highway speeds. This condition can be alleviated to some extent by repositioning the front number plate as illustrated in Fig. 1.

It is recommended that two small holes are drilled in the front bumper and the plate attached by self-tapping screws. The original mounting brackets can be discarded.



FIG. 1

J.P.