

*Date of Issue: May, 1947*

**Service Information Sheet No. 69**

**DISTRIBUTORS**

When fitting the gear to a distributor spindle, .005 in. end play should be left as shown in the sketch below.

