

All 1974 vehicle customers should receive a Passport to Service clearly indicating "1974" on the cover.

If by chance you have supplied a purchaser of a 1974 car with other than this 1974 Passport, please arrange to make an exchange with the correct passport.

REK