

TECHNICAL SERVICE BULLETIN

NO. 75-A-1



Austin MG

February, 1975

SUBJECT:

FAN BELTS

MODELS:

MARINA AND MGB

It is possible that some confusion exists at dealer level with regard to the correct fan belt to be used on the Marina and MGB.

Due to different diameters of alternator pulleys, it has been necessary to specify fan belts of different lengths. The following information should clear up any misunderstanding.

	<u>UP TO VIN</u>	<u>ALTERNATOR PULLEY DIAMETER</u>	<u>BELT LENGTH</u>	<u>UNIPART NO.</u>	<u>B.L. PART NO.</u>
Marina 2 Dr.	AH2DDE14379	2.75"	35.5"	GFB 176	13H4366
Marina 4 Dr.	AH4SDE14379	2.75"	35.5"	GFB 176	13H4366
MGB	GHN5UE347179	2.75"	35.5"	GFB 176	13H4366

FROM ABOVE VIN'S TO:

Marina 2 Dr.	AH2DDF101M	2.375"	35"	GFB 196	13H8309
Marina 4 Dr.	AH4SDF100M	2.375"	35"	GFB 196	13H8309
MGB	GHN5UF367901G	2.375"	35"	GFB 196	13H8309

1975 SPECIFICATIONS

Marina 2 Dr.	AH2DDF101M	37.38"	GFB 205
Marina 4 Dr.	AH4SDF100M	37.38"	GFB 205
MGB	GHN5UF367901G	37.38"	GFB 205

J.P.