

TECHNICAL SERVICE BULLETIN

75-B-5

NO.



Austin MG

May, 1975

SUBJECT:

MODELS:

ELECTRONIC TYPE IGNITION SYSTEM

MIDGET

The 1975 Midget 1500 CC is now equipped with a Lucas electronic ignition system. Please note the amplifier unit which is attached to the distributor body will not be serviced separately. Therefore, should this component require replacement during the warranty period, a complete distributor assembly must be installed.

Dealers are requested to return the displaced units (amplifier and distributor assembly) to their distributors in accordance with the current vendor warranty arrangements.

J.P.